

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

ORIGINAL

FIELD NOTES

OF

THE DEPENDENT RESURVEY OF
A PORTION OF THE SUBDIVISIONAL LINES,

AND

THE SUBDIVISION OF SECTION 23,

IN

TOWNSHIP 31 SOUTH, RANGE 25 EAST,

OF THE SALT LAKE MERIDIAN
IN THE STATE OF UTAH

EXECUTED BY

Scott A. Burkhardt
Cadastral Surveyor

Under Special Instructions dated and approved ***November 12, 2013***, which provided for the surveys included under Group Number ***1252***, and Assignment Instructions dated ***November 12, 2013***.

Survey Commenced, ***November 12, 2013***
Survey Completed, ***May 13, 2014***

INDEX DIAGRAM

TOWNSHIP 31 SOUTH, RANGE 25 EAST, SALT LAKE MERIDIAN, UTAH

6	5	4	3	2	1
7	8	9	10	11	12
18	17	16	15	14	13
19	20	21	22	9 23	24
30	29	28	27	6 26	25
31	32	33	34	35	36

The Subdivision of Section 23.....10

TOWNSHIP 31 SOUTH, RANGE 25 EAST, SALT LAKE MERIDIAN, UTAH

The following field notes are those of the dependent resurvey of a portion of the subdivisional lines, and the subdivision of section 23, in T. 31 S., R. 25 E., Salt Lake Meridian, Utah.

HISTORY OF SURVEYS

Surveyed by		Retr. or Resurveyed by	
SOUTH BOUNDARY			
All	E. Buettner	1884	
All		M.D. Heist & E.B. Andrews	1911
Portion		R. Gentry	1917
EAST BOUNDARY			
Portion	E. Buettner	1884	
All	R. Gentry	1917	R. Gentry 1917
WEST BOUNDARY			
Portion	E. Buettner	1884	
All	T.C. Rathbone & H.G. Mason	1916	
NORTH BOUNDARY (Sixth Standard Parallel South)			
All	T.C. Rathbone & H.G. Mason	1916	
SUBDIVISION			
All	R. Gentry	1917	
PRIVATE AND LOCAL SURVEYS IN AND ADJACENT TO SEC. 23			

A survey of "Sections 13, 14, 24, T31S, R25E, SLB&M" was performed by Douglas E. Pehrson, Utah RLS No. 155675, in July, 2005 and recorded at the San Juan County Recorder's Office on July 30, 2006, as Record of Survey No. 533.

A survey of "Section 23, T31S, R25E, SLB&M" was performed by Douglas E. Pehrson, Utah RLS No. 155675, in June, 2006 and recorded at the San Juan County Recorder's Office on June 27, 2007, as Record of Survey No. 647.

A survey of "Section 24, T31S, R25E, SLB&M" was performed by Douglas E. Pehrson, Utah RLS No. 155675, in September, 2009 and recorded at the San Juan County Recorder's Office on September 6, 2009, as Record of Survey No. 807.

A survey "situated within the E 1/2 of Section 24, T31S, R25E, Salt Lake Meridian" was performed by Clyde J. King, Utah RLS No. 366504, for Absolute Surveying and Mapping, Inc., in October, 2009 and recorded at the San Juan County Recorder's Office on October 7, 2009, as Record of Survey No. 819.

A survey of "Section 24, T31S, R25E, SLB&M" was performed by Douglas E. Pehrson, Utah RLS No. 155675, in September, 2010 and recorded at the San Juan County Recorder's Office on September 10, 2010, as Record of Survey No. 850.

TOWNSHIP 31 SOUTH, RANGE 25 EAST, SALT LAKE MERIDIAN, UTAH

PRIVATE AND LOCAL SURVEYS CONTINUED

A survey of "SE 1/4 SE 1/4 and SW 1/4 SE 1/4 Section 24, T31S, R25E, SLM" was performed by Gerald G. Huddleston, Utah RLS No. 161297, for Brown, Gilbreth & Hemphill, in June, 2011 and recorded at the San Juan County Recorder's Office on June 2, 2011, as Record of Survey No. 877.

TOWNSHIP 31 SOUTH, RANGE 25 EAST, SALT LAKE MERIDIAN, UTAH

The survey was executed in accordance with the specifications set forth in the Manual of Surveying Instructions, 2009, and the Special Instructions for Group No. 1252, dated November 12, 2013.

The direction of each line is with reference to the true meridian, determined by Global Positioning System (GPS) utilizing Real-Time Kinematic (RTK) techniques throughout the survey. The positional accuracy of this survey complies with the *Standards for the Positional Accuracy of Cadastral Surveys when using Global Navigation Satellite Systems (GNSS)*, dated February 23, 2009. Trimble model R8 GPS receivers were used for field collection. Cadastral Automated Plat Drafting (CAPD) software was the primary software utilized for project calculations.

Preliminary to the resurvey, the lines of the prior surveys were retraced and a search was made for all corners and other calls of record. Identified corners were remonumented in their original positions. Lost corners were reestablished and remonumented at proportionate positions based on the official record. The retracement data were thoroughly verified and only the true line field notes are given herein.

Geodetic Control Network was derived from GPS static observations, post processed by the National Geodetic Survey, Online Positioning User Service (OPUS), utilizing Continuously Operating Reference Stations (CORS): DH6912 MC02 MESA CNTY COOP CORS ARP, DH6916 MC04 MESA CNTY COOP CORS ARP, and DH6918 MC05 MESA CNTY COOP CORS ARP.

The geographic position of the corner of sections 13, 14, 23, and 24, T. 31 S., R. 25 E., as determined by direct RTK methods from the National Geodetic Survey OPUS solution, is as follows:

Latitude: **38°05'00.058" N.**,
Longitude: **109°08'10.449" W.**, N.A.D. 83 (2011), EPOCH: 2010.00,
Network Accuracy = 0.200 meter at 95% confidence.

The geographic position of the corner of sections 22, 23, 26, and 27, T. 31 S., R. 25 E., as determined by direct RTK methods from the National Geodetic Survey OPUS solution, is as follows:

Latitude: **38°04'07.779" N.**,
Longitude: **109°09'16.340" W.**, N.A.D. 83 (2011), EPOCH: 2010.00,
Network Accuracy = 0.200 meter at 95% confidence.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,
TOWNSHIP 31 SOUTH, RANGE 25 EAST, SALT LAKE MERIDIAN, UTAH

CHAINS

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 31 S., R. 25 E., Salt Lake Meridian, Utah

The Reestablishment of the Survey Executed by R. Gentry in 1917

Beginning at the corner of sections 23, 24, 25, and 26, monumented with a rebar, 5/8 inch diameter, firmly set, buried 5 inches below the road surface, at the intersection of improved gravel roads, 25 feet wide, bearing north, south, east, and west. There is no remaining evidence of the 1917 iron post or bearing trees. This position is harmoniously related to existing corners and is accepted as a perpetuation of the original corner.

From which

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 23 inches in the ground, with magnet at base, for a reference monument, bears N.32°33.2'E., 77.1 links distance, with an aluminum cap marked RM T31S R25E S24 2014, with an arrow pointing toward the corner with 50.9 FT. TO COR. marked along it. Set a steel fence post west of the corner. Corner is located west of a fence line, wood post and two-strand barbed wire, extending north-south.

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 25 inches in the ground, with magnet at base, for a reference monument, bears N.60°34.2'W., 100.4 links distance, with an aluminum cap marked RM T31S R25E S23 2014, with an arrow pointing toward the corner with 66.3 FT. TO COR. marked along it. Set a steel fence post north of the corner. Corner is located north of an improved gravel road, 22 feet wide, bearing east-west.

From the corner, an unrecorded washer, 1 1/2 inches diameter, nailed to a fence post, bears S.45°15.7'E, 73.4 links distance, marked CO 33190 UT 366504-2201.

N. 0°04.2'W., between sections 23 and 24.

- 20.004 Point for the S 1/16 section corner of sections 23 and 24. Falls in an improved gravel road, 22 feet wide, bearing north and south. Set a 10 inch spike, 4 inches below the road surface.

From which

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 25 inches in the ground, with magnet at base, for a reference monument, bears S.47°21.5'W., 67.3 links distance, with an aluminum cap marked RM T31S R25E S23 2014, with an arrow pointing toward the corner with 44.4 FT. TO COR. marked along it. Set a steel fence post north of the corner. Corner is located west of an improved gravel

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,
TOWNSHIP 31 SOUTH, RANGE 25 EAST, SALT LAKE MERIDIAN, UTAH

CHAINS

road, 22 feet wide, bearing north-south.

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 25 inches in the ground, with magnet at base, for a reference monument, bears N.45°1.7'W., 65.9 links distance, with an aluminum cap marked RM T31S R25E S23 2014, with an arrow pointing toward the corner with 43.5 FT. TO COR. marked along it. Set a steel fence post north of the corner. Corner is located west of an improved gravel road, 22 feet wide, bearing north-south.

- 40.008** The 1/4 section corner of sections 23 and 24, monumented with a rebar, 5/8 inch diameter, firmly set, flush with the road surface, with a broken plastic yellow cap with illegible writing. There is no remaining evidence of the 1917 iron post or bearing trees. This is accepted as a careful and faithful determination of the position of the corner.

From which

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 24 inches in the ground, with magnet at base, for a reference monument, bears S.42°58.7'W. 77.0 links distance, with an aluminum cap marked RM T31S R25E S23 2014, with an arrow pointing toward the corner with 50.8 FT. TO COR. marked along it. Set a steel fence post north of the corner. Corner is located approximately 14 feet west of the west edge of an improved gravel road, 22 feet wide, bearing north-south.

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 24 inches in the ground, with magnet at base, for a reference monument, bears N.45°56.0'W., 81.2 links distance, with an aluminum cap marked RM T31S R25E S23 2014, with an arrow pointing toward the corner with 53.6 FT. TO COR. marked along it. Set a steel fence post north of the corner. Corner is located approximately 15 feet west of the west edge of an improved gravel road, 22 feet wide, bearing north-south.

N. 0°03.8'W., beginning new measurement.

- 19.996** The N 1/16 section corner of sections 23 and 24, established by Douglas E. Pehrson, Utah RLS No. 155675, monumented with a rebar, 5/8 inch diameter, firmly set, buried 1 inch below the road surface, in an improved gravel road, 22 feet wide, bearing north-south, with a plastic yellow cap marked UTAH LS155675, set in June, 2006, at proportionate distance, as recorded on his plat, San Juan County Record of Survey No. 647. This is accepted as a careful and faithful determination of the position of the corner.

From which

A rebar, 5/8 inch diameter, firmly set, projecting 3 inches

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,
TOWNSHIP 31 SOUTH, RANGE 25 EAST, SALT LAKE MERIDIAN, UTAH

CHAINS

above the ground, for a reference monument, bears N.
89°47.8' E., 37.8 links distance, with a yellow plastic cap
marked UTAH LS155675. Set a steel fence post north of the
corner.

A rebar, 5/8 inch diameter, firmly set, projecting 2 inches
above the ground, for a reference monument, bears N.
69°30.8' W., 53.5 links distance, with a yellow plastic cap
marked UTAH LS155675. Set a steel fence post south of the
corner.

N. 0°02.5' W., beginning new measurement.

19.997 The corner of sections 13, 14, 23, and 24, determined at record
bearing and distance from the remaining 1917 bearing tree,

A pinon, 13 inches diameter, bears S. 59°15' E., 38 links
distance, marked T31S R25E S24 BT.

Point falls at the intersection of improved gravel roads, 22
feet wide, bearing north, south, and west. Set a 10 inch spike,
4 inches below the road surface.

From which

An aluminum post, 30 inches long, 2 1/2 inches diameter, set
24 inches in the ground, with magnet at base, for a
reference monument, bears N. 43°26.7' E., 47.3 links
distance, with an aluminum cap marked RM T31S R25E S13
2014, with an arrow pointing toward the corner with 31.2
FT. TO COR. marked along it. Set a steel fence post west of
the corner. Corner is located in a fence line, wood post
and two-strand barbed-wire, extending north-south.

An aluminum post, 30 inches long, 2 1/2 inches diameter, set
25 inches in the ground, with magnet at base, for a
reference monument, bears N. 60°24.2' W., 63.8 links
distance, with an aluminum cap marked RM T31S R25E S14
2014, with an arrow pointing toward the corner with 42.1
FT. TO COR. marked along it. Set a steel fence post north
of the corner. Corner is located in a fence line, wood post
and three-strand barbed-wire, extending east-west.

From the corner of sections 23, 24, 25, and 26.

S. 89°53.9' W., between sections 23 and 26.

19.985 Point for the E 1/16 section corner of sections 23 and 26. Not
monumented.

39.970 The 1/4 section corner of sections 23 and 26, determined at
record bearing and distance from the remaining 1917 bearing tree,

A juniper, 16 inches diameter, bears S. 10°15' W., 56 links

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,
TOWNSHIP 31 SOUTH, RANGE 25 EAST, SALT LAKE MERIDIAN, UTAH

CHAINS

distance, with a healed-over blaze (Record: marked 1/4 S26 BT).

Point falls in an improved gravel road, 25 feet wide, bearing east and west. Find the original 1917 iron post, bent and lying loose in a tree nearby. Set an 8 inch spike, 5 inches below the road surface. Remove 1917 iron post.

From which

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 24 inches in the ground, with magnet at base, for a reference monument, bears S.41°49.2'W., 69.9 links distance, with an aluminum cap marked RM T31S R25E S26 2014, with an arrow pointing toward the corner with 46.1 FT. TO COR. marked along it. Set a steel fence post west of the corner. Corner is located approximately 16 feet south of the south edge of an improved gravel road, 22 feet wide, bearing east-west.

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 25 inches in the ground, with magnet at base, for a reference monument, bears N.51°31.0'W., 78.6 links distance, with an aluminum cap marked RM T31S R25E S23 2014, with an arrow pointing toward the corner with 51.9 FT. TO COR. marked along it. Set a steel fence post east of the corner. Corner is located approximately 18 feet north of the north edge of an improved gravel road, 22 feet wide, bearing east-west.

S. 89°53.0'W., beginning new measurement.

19.990 Point for the W 1/16 section corner of sections 23 and 26. Not monumented.

39.980 The corner of sections 22, 23, 26, and 27, monumented with an iron post, 2 inches diameter, firmly set but brass cap and top of post sheared off, buried 12 inches below the road surface, in an improved gravel road, 25 feet wide, bearing east and west. Leave in place.

From which the remaining 1917 bearing tree

A cedar, 23 inches diameter, bears N.26°30'W., 64 links distance, with a healed-over blaze (Record: marked T31S R25E S22 BT).

From which

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 25 inches in the ground, with magnet at base, for a reference monument, bears S.40°33.7'W., 60.5 links distance, with an aluminum cap marked RM T31S R25E S27 2014, with an arrow pointing toward the corner with 40.0 FT. TO COR. marked along it. Set a steel fence post west of

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,
TOWNSHIP 31 SOUTH, RANGE 25 EAST, SALT LAKE MERIDIAN, UTAH

CHAINS

the corner. Corner is located approximately 13 feet south of the south edge of an improved gravel road, 22 feet wide, bearing east-west, and 2 feet north of a fence line, wood post and four-strand barbed wire, extending east-west.

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 25 inches in the ground, with magnet at base, for a reference monument, bears N.41°17.6'W., 43.6 links distance, with an aluminum cap marked RM T31S R25E S22 2014, with an arrow pointing toward the corner with 28.8 FT. TO COR. marked along it. Set a steel fence post east of the corner. Corner is located approximately 10 feet north of the north edge of an improved gravel road, 22 feet wide, bearing east-west.

N. 0°02.6' W., between sections 22 and 23.

20.016 Point for the S 1/16 section corner of sections 22 and 23.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, magnet at base, with aluminum cap marked

T31S R25E
S 1/16
S22 | S23
2014

Set a steel fence post west of the corner.

Corner is located in gently rolling ground, with sagebrush and juniper trees, approximately 10 feet west of an unimproved dirt road, 10 feet wide, bearing north-south.

40.032 Point for the 1/4 section corner of sections 22 and 23, at proportionate distance. There is no remaining evidence of the 1917 iron post or bearing trees.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 11 inches in the ground, magnet at base, in a mound of stone, 3 feet diameter, to cap, with aluminum cap marked

T31S R25E
1/4
S22 | S23
2014

Set a steel fence post north of the corner.

Corner is located in gently rolling ground, with sagebrush and juniper trees, approximately 10 feet west of an unimproved dirt

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,
TOWNSHIP 31 SOUTH, RANGE 25 EAST, SALT LAKE MERIDIAN, UTAH

CHAINS

road, 10 feet wide, bearing north-south.

- 60.048** Point for the N 1/16 section corner of sections 22 and 23. Not monumented.

From the corner, a rebar, 5/8 inch diameter, firmly set, projecting 3 inches above the ground, bears N.76°07.7'E., 2.0 links distance, with a plastic yellow cap with illegible markings; set in June, 2006, by Douglas E. Pehrson, Utah RLS No. 155675, as recorded on his plat, San Juan County Record of Survey No. 647, using improper proportioning procedures (original evidence missed for a controlling corner), and was not utilized during the course of this resurvey.

- 80.064** The corner of sections 14, 15, 22, and 23, monumented with an iron post, 2 inches diameter, firmly set, projecting 6 inches above the ground, with brass cap marked as described in the official record of the 1917 survey.

There is no remaining evidence of the 1917 bearing trees.

Set a steel fence post east of the corner.

Corner lies near several large boulders, north of an improved gravel road, 22 feet wide, bearing east-west.

From the corner of sections 13, 14, 23, and 24.

S. 89°56.1' W., between sections 14 and 23.

- 19.977** Point for the E 1/16 section corner of sections 14 and 23. Not monumented.

- 39.954** Point for the 1/4 section corner of sections 14 and 23, at proportionate distance. There is no remaining evidence of the 1917 iron post or bearing trees. Point falls in an improved gravel road, 20 feet wide, bearing east-west. Set a 60d spike, 6 inches below the road surface.

From which

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 27 inches in the ground, with magnet at base, for a reference monument, bears N.44°52.8'E., 72.6 links distance, with an aluminum cap marked RM T31S R25E S14 2014, with an arrow pointing toward the corner with 47.9 FT. TO COR. marked along it. Set a steel fence post east of the corner. Corner is located in the north shoulder of an improved gravel road, 20 feet wide, bearing east-west.

An aluminum post, 30 inches long, 2 1/2 inches diameter, set 27 inches in the ground, with magnet at base, for a reference monument, bears S.46°03.2'E., 73.5 links distance, with an aluminum cap marked RM T31S R25E S23 2014, with an arrow pointing toward the corner with 48.5

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,
TOWNSHIP 31 SOUTH, RANGE 25 EAST, SALT LAKE MERIDIAN, UTAH

CHAINS

FT. TO COR. marked along it. Set a steel fence post north of the corner. Corner is located in the south shoulder of an improved gravel road, 20 feet wide, bearing east-west.

59.931 Point for the W 1/16 section corner of sections 14 and 23. Not monumented.

79.908 The corner of sections 14, 15, 22, and 23.

The Subdivision of Section 23,
T. 31 S., R. 25 E., Salt Lake Meridian, Utah

From the 1/4 section corner of sections 23 and 26.

N. 0°03.3 W., on the north-south centerline of section 23.

20.008 Point for the center S 1/16 section corner of section 23.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 27 inches in the ground, magnet at base, with aluminum cap marked

T31S R25E
C
S 1/16 | S23
C
2014

Set a steel fence post northwest of the corner.

Corner is located on a gentle south slope, in open terrain, with sagebrush.

40.016 Point for the center 1/4 section corner of section 23, at intersection with the east-west centerline.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 22 inches in the ground, magnet at base, with aluminum cap marked

T31S R24E
C 1/4 S23
2014

Set a steel fence post north of the corner.

Corner is located on gently-rolling ground, with juniper trees and sagebrush.

60.022 Point for the center N 1/16 section corner of section 23.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 10 inches in the ground to bedrock, magnet at base, in a mound of

THE SUBDIVISION OF SECTION 23,
TOWNSHIP 31 SOUTH, RANGE 25 EAST, SALT LAKE MERIDIAN, UTAH

CHAINS

stone, 3 feet diameter, to cap, with aluminum cap marked

T31S R25E
C
N 1/16 | S23
C
2014

Set a steel fence post east of the corner.

Corner is located in dense pinon and juniper trees.

80.028 The 1/4 section corner of sections 14 and 23.

From the 1/4 section corner of sections 23 and 24.

S. 89°54.4' W., on the E-W centerline of section 23.

19.978 Point for the center E 1/16 section corner of section 23.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 22 inches in the ground, with a magnet at base, in a collar of stone, 2 feet diameter, with aluminum cap, marked

T31S R25E
E 1/16
C ————— C
S23
2014

Set a steel fence post west of the corner.

Corner is located in gently-rolling ground, with scattered juniper trees, approximately 8 feet north of an unimproved dirt road.

39.956 The center 1/4 section corner of section 23.

59.940 Point for the center W 1/16 section corner of section 23.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 25 inches in the ground, with a magnet at base, with aluminum cap, marked

T31S R25E
W 1/16
C ————— C
S23
2014

Set a steel fence post northwest of the corner.

THE SUBDIVISION OF SECTION 23,
TOWNSHIP 31 SOUTH, RANGE 25 EAST, SALT LAKE MERIDIAN, UTAH

CHAINS

Corner is located in flat, level ground with scattered juniper trees and sagebrush.

79.924 The 1/4 section corner of sections 22 and 23.

From the center E 1/16 section corner of section 23.

N. 0°03.2' W., on the north-south centerline of the NE 1/4 of section 23.

20.001 Point for the NE 1/16 section corner of section 23, at the intersection with the east-west centerline of the NE 1/4 of section 23. Not monumented.

40.003 The point for the E 1/16 section corner of sections 14 and 23.

From the N 1/16 section corner of sections 23 and 24.

S. 89°55.3' W., on the east-west centerline of the NE 1/4 of section 23.

19.974 The point for the NE 1/16 section corner of section 23.

39.951 The center N 1/16 section corner of section 23.

From the point for the E 1/16 section corner of sections 23 and 26.

N. 0°03.8' W., on the north-south centerline of the SE 1/4 of section 23.

20.006 Point for the SE 1/16 section corner of section 23, at the intersection with the east-west centerline of the SE 1/4 of section 23.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 25 inches in the ground, magnet at base, with aluminum cap marked

T31S R25E

SE 1/16 S23

2014

Set a steel fence post north of the corner.

Corner is located in fairly flat, level ground, with sagebrush.

40.012 The center E 1/16 section corner of section 23.

From the S 1/16 section corner of sections 23 and 24.

S. 89°54.2' W., on the east-west centerline of the SE 1/4 of

THE SUBDIVISION OF SECTION 23,
TOWNSHIP 31 SOUTH, RANGE 25 EAST, SALT LAKE MERIDIAN, UTAH

CHAINS

section 23.

19.981 The SE 1/16 section corner of section 23.

39.962 The center S 1/16 section corner of section 23.

From the point for the W 1/16 section corner of sections 23 and 26.

N. 0°03.0' W., on the north-south centerline of the SW 1/4 of section 23.

20.012 Point for the SW 1/16 section corner of section 23, at the intersection with the east-west centerline of the SW 1/4 of section 23. Not monumented.

40.024 The center W 1/16 section corner of section 23.

From the center S 1/16 section corner of section 23.

S. 89°53.7' W., on the east-west centerline of the SW 1/4 of section 23.

19.987 The point for the SW 1/16 section corner of section 23.

39.974 The S 1/16 section corner of sections 22 and 23.

From the center W 1/16 section corner of section 23.

N. 0°03.0' W., on the north-south centerline of the NW 1/4 of section 23.

20.011 Point for the NW 1/16 section corner of section 23, at the intersection with the east-west centerline of the NW 1/4 of section 23.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 27 inches in the ground, magnet at base, with aluminum cap marked

T31S R25E

NW 1/16 S23

2014

Set a steel fence post east of the corner.

Corner is located in pinon and juniper trees, and sagebrush.

40.022 The point for the W 1/16 section corner of sections 14 and 23.

From the center N 1/16 section corner of section 23.

THE SUBDIVISION OF SECTION 23,
TOWNSHIP 31 SOUTH, RANGE 25 EAST, SALT LAKE MERIDIAN, UTAH
CHAINS

S. 89°55.3' W., on the east-west centerline of the NW 1/4 of
section 23.

19.980 The NW 1/16 section corner of section 23.

39.960 The point for the N 1/16 section corner of sections 22 and 23.

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FIELD ASSISTANTS

Name	Capacity
Phil Freiberg	Survey Technician

CERTIFICATE OF SURVEY

I, **Scott A. Burkhardt, Cadastral Surveyor**, HEREBY CERTIFY upon honor, that in pursuance of Special Instructions bearing the date of **November 12, 2013**, I have **dependently resurveyed a portion of the subdivisional lines, and subdivided section 23, in Township 31 South, Range 25 East**, of the **Salt Lake Meridian**, in the State of **Utah**, which are represented in the foregoing field notes as having been executed by me and under my direction; and that said survey has been made in strict conformity with said Special Instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, and in specific manner described in the foregoing field notes.

May 11, 2015
Date

Scott A. Burkhardt
Cadastral Surveyor

CERTIFICATE OF APPROVAL

BUREAU OF LAND MANAGEMENT
Salt Lake City, Utah

The foregoing field notes of the **dependent resurvey of a portion of the subdivisional lines, and the subdivision of section 23, in Township 31 South, Range 25 East, Salt Lake Meridian, Utah**, executed by **Scott A. Burkhardt, Cadastral Surveyor**, having been critically examined and found correct, are hereby approved.

May 12, 2015
Date

Daniel W. Webb
Chief Cadastral Surveyor for Utah